

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2020

Submitted Date:

08/12/2020

Document Number:

693902120

**FIELD INSPECTION FORM**

Loc ID 326512 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ray, Mandy	(505) 599-4083	mray@hilcorp.com	<a href="#">All Inspections</a>
Shorty, Priscilla		pshorty@hilcorp.com	<a href="#">All SW Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89125	WELL	PR	03/08/2000	GW	067-08229	HUBER-BURKETT 3-25	RI

**General Comment:**

On 8/11/2020 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

- Remove and properly dispose of wood debris by 8/28/2020.
- Stormwater controls need to be installed to stabilize erosion within the project area by 9/12/2020. Wattles are not sufficient BMPs in eroding areas.

See below, and attached photos for additional detail.

**Inspected Facilities**

Facility ID: 89125 Type: WELL API Number: 067-08229 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment Wood debris observed within the southern project area.

Corrective Action Remove and properly dispose of wood debris.

Date **08/28/2020**

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_



<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <span style="color: blue;">Wattles in the southern project area are full of sediment and no longer functioning. Wattles were installed to address corrective action identified during a 2018 inspection. However wattles do not appear to be adequate BMPs in these areas.</span>						
Corrective Action: <span style="color: red;">Stormwater controls need to be installed to stabilize erosion within the project area.</span>						Date: 09/12/2020
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402465145	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5222186">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5222186</a>
693902121	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5222181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5222181</a>