

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2020

Submitted Date:

08/28/2020

Document Number:

693503415

FIELD INSPECTION FORM

Loc ID 318149 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS
Lara-Mesa,	303-825-4822	cogcc@kpk.com	All inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240713	WELL	PR	10/01/2018	OW	123-08501	OUR DIANE 32-27	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate KPK has installed company sticker over PDC sign.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around 55gal drum. around PU motor and exhaust pipe.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: <u>11/27/2020</u>
Type	OTHER		
Comment:	Mechanical issue. Pumping unit motor appears to be leaking.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>11/27/2020</u>
Type	OTHER		
Comment:	Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B		Date: <u>11/27/2020</u>
Type	DEBRIS		
Comment:	Dead weeds on location and around equipment.		
Corrective Action:	Comply with rule 603f		Date: <u>11/27/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack # 1			

Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240713 Type: WELL API Number: 123-08501 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 8-26-2020
 Complaint Contacted:
 Date: 8-27-2020 Time: 1:19PM via Phone
 Location ID # 318149,318641,318642
 Location name: Our Diana #32-27, Rocky Mountain Fuel CO H #1, Rocky Mountain Fuel CO H #2
 Inspection Document # 693503415, 693503417,693503419
 Complaint Document # 200449156
 Nature of Complaint: Maintenance and production
 Field Inspector Actions:
 On 8-26-2020, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to maintenance and production.
 On 8-27-2020, I attempted to make contact with the complainant contact Paula who stated concerns with non-production of wells and maintenance issues.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I observed several maintenance issues with the Our Dian and Rocky Mountain Fuel CO H#1. Corrective actions have been issued for observed maintenance issues. In regards to production, production, records submitted to the COGCC show production as of 6-20. These are all KP Kauffman wells.
 Weather conditions: Clear and location dry.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday August 27, 2020 at approximately 12:22PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Our Diane #32-27 Operator: KP Kauffman- API#: 05-123-08501 County: Weld While there, I observed a producing well site. During this inspection the following possible compliance issues were observed: Debris: Rule 603 f Corrective action date of 11-27-20 See photos 1,2 Mechanical issue: Rule 605 d Corrective action date of 11-27-20 see photo 4 Stained soil: rule 907 A Corrective action date of 11-27-20 see Photos 2,3,4 Material handling: Rule 1002 f B Corrective action date of 11-27-20 See Photo 2 Weather conditions: Clear and location dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402477706	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234761
693503416	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234757