

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 8/26/2020
All Photos taken by Kris Neidel



Photo #1 Overview of the Bowl Area looking northeast. Note tilled soil in center of bowl. Soil will need to be imported to restore the original contour of the bowl.

Inspection Photos

Spill ID 449632

Remediation Project 10149

Inspection Date: 8/26/2020

All Photos taken by Kris Neidel



Photo #2 Holes were drilled with a gas powered auger, loose soil removed with a post hole digger, then soils taken from the wall of the hole at the appropriate depth.

Inspection Photos

Spill ID 449632

Remediation Project 10149

Inspection Date: 8/26/2020

All Photos taken by Kris Neidel



Photo #3 Photo of the spill path below the Bowl, referred to as Division 1 in Remediation document. This area has been tilled regularly with a skid steer mounted implement. The entire spill path is free of any visible hydrocarbon.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 8/26/2020
All Photos taken by Kris Neidel



Photo #4 of Division 1. No vegetation is present in this division due to the frequency of tilling (see remediation project for tilling details). The entire spill path is free of any visible hydrocarbon.

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 8/26/2020
All Photos taken by Kris Neidel



Photo #5 Chevron Staff collecting a sample in Division 3.