

WELL SITE INSPECTION FORM



00269835

Well Name SWEDLUND #1 34751 API Number 05 -
 Operator WESTERN OPER. Permit #
 Location SWNW4-9N-53W County LOGAN
 Field WINDSONG Inspector R. Vansickle
 AL/PA/DA Inspection Results: Well Status:
 Pass(Y) Fail(N) Date FN FD WO PR ✓ SI

=====

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
 Consistent with APD casing Program? YES NO Returns
 Rig BOP'S Contact

Date of Inspection Before/During/After Completion 4-18-90

Prod. Csg. Set? ✓ Completion Rig/Activity
 Drilling Pits: Closed ✓ Open Wellhead Installed Y ✓ N
 Tank ID: Yes ✓ No N/A Skim Tank/Pit: 6x6x4' Prod. Tanks: (2) 300 BBLs
 Equipment FV-HT Meter Run: Yes No ✓
 Bradenhead Press: Fluid: No Yes Type Well Cat.

AL/PA/DA Inspection

Date Plugged: Date Permit Expired:
 Hole Plugged: Yes No Pits Backfilled: Yes No
 Material Buried: Yes No N/A Site Clean: Yes No
 Bond Release OK: Yes No Fed Hole Marker: Yes No

Date of Safety/Status Inspection

Comments: PIT IS COVERED W/OIL³²⁵, TOO MUCH GAS TO SKIM PIT.
NO BERM. NO SIGN.

518 17th St #1680
Denver, 80202

7BOPD, 100BWPD.

Violations: Yes ✓ No Notice Sent: Yes ✓ No Date Sent: 5-21

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director
DENNIS R. BICKNELL
Deputy Director

(303) 894-2100

ROY ROMER
Governor

May 18, 1990


Western Operating
518 17th Street, #1680
Denver, CO 80202

Dear Sir:

In April I inspected the Swedlund #1 SWNW4-9N-53W in Logan County. At that time your retaining pit had oil on it and your skim pit was not covered. Rule 325 requires that pits be kept free of oil and that accumulations be removed within 10 days. A condition of the approval of this pit permit required that the skim pit be covered. Presence of waterfowl at or near this site makes overhead cover a must. Your production tanks have no berms in place as required by Rule 604.a(4).

You are hereby directed to correct these deficiencies within 30 days. No other response is necessary, however if you have questions or comments about this letter you may reach me at the above address or phone number.

Sincerely,



Robert J. Van Sickle
Field Engineer

rjv/48v