

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402492553  
Date Received:  
09/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

|                     |                       |                                    |
|---------------------|-----------------------|------------------------------------|
| Contact Name        | Phone                 | Email                              |
| <u>Alyssa Beard</u> | <u>(303) 244-8114</u> | <u>abeard@foundationenergy.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 696302422  
Inspection Date: 09/08/2020 FIR Submit Date: 09/08/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 435380

Location Name: WICKSTROM Number: 6 CTB County: \_\_\_\_\_  
Qtrqr: Lot 4 Sec: 6 Twp: 7N Range: 59W Meridian: 6  
Latitude: 40.610860 Longitude: -104.025991

FACILITY - API Number: 05-123-00 Facility ID: 435380

Facility Name: WICKSTROM Number: 6 CTB  
Qtrqr: Lot 4 Sec: 6 Twp: 7N Range: 59W Meridian: 6  
Latitude: 40.610860 Longitude: -104.025991

CORRECTIVE ACTIONS:

1 CA# 141768

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 324 A.a Date: 09/23/2020

Response: CA COMPLETED Date of Completion: 09/15/2020

Operator Comment: The day tank was not actually Foundation's, and we had it removed from the location. Tank removed shown in attached photo.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

3 CA# 141770

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 09/23/2020

Response: CA COMPLETED

Date of Completion: 09/15/2020

Operator Comment: Stained soil at north tank loadlines was removed. Please see attached photo.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: \_\_\_\_\_

Title: EHSR Manager

Date: 9/18/2020 9:18:22 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>            |
|------------------------|-------------------------------|
| 402492563              | Stained soil removed          |
| 402492564              | Day tank removed              |
| 402492565              | Pit netting fixed - Wickstrom |

Total Attach: 3 Files