

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402424494

Date Received:

06/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901534

Inspection Date: 03/16/2020

FIR Submit Date: 03/17/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333627

Location Name: COLORADO 32-7-N32N7W Number: 3SWNE County: LA PLATA

Qtrqr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049361 Longitude: -107.591988

FACILITY - API Number: 05-067- -00 Facility ID: 216253

Facility Name: SCHOFIELD A Number: 1

Qtrqr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049361 Longitude: -107.591988

CORRECTIVE ACTIONS:

1 ☒ CA# 137265

Corrective Action: Remove and properly dispose of junk and debris. Corrective action is backdated to previous corrective action date as debris remains on location.

Date: 11/01/2018

Response: CA COMPLETED

Date of Completion: 06/09/2020

Operator Comment: "Junk and Debris" was land owner piping placed on location for ease of access to it when needed. Landowner items were removed from location see attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 137266

Corrective Action: Stormwater controls (ie BMPs) need to be repaired/replaced as needed. Erosion controls (ie: revegetation, mulching, blankets) are needed on bare soils on the well pad fill slopes.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 06/09/2020

Operator Comment: Seeding completed after consulting with landowner of their desired seed mix. Landowner refused to allow native brush seed and would only approve seed mix that could be utilized for agricultural cattle operations in the future. Seeding and mulching completed see attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions addressed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 6/17/2020 10:29:00 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402424494	FIR RESOLUTION SUBMITTED
402424510	Seeding completion
402424511	Landowne item removal

Total Attach: 3 Files