

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402453705

Date Received:  
07/27/2020

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
.		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901895  
Inspection Date: 06/11/2020 FIR Submit Date: 06/12/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325675

Location Name: FEDERAL LAND BANK 'D' UT-M34N9W Number: 36SESE County: LA PLATA  
Qtrqtr: SESE Sec: 36 Twp: 34N Range: 9W Meridian: M  
Latitude: 37.143385 Longitude: -107.772720

FACILITY - API Number: 05-067-00 Facility ID: 215214

Facility Name: FEDERAL LAND BANK D Number: 1  
Qtrqtr: SESE Sec: 36 Twp: 34N Range: 9W Meridian: M  
Latitude: 37.143385 Longitude: -107.772720

CORRECTIVE ACTIIONS:

1  CA# 139717

Corrective Action: Control weeds. Corrective action date is shortened to prevent spread of seed from mature thistle plants. Date: 06/30/2020

Response: CA COMPLETED Date of Completion: 07/07/2020

Operator Comment: Weeds treated and FIRR #402438388 filed for weed closure action item see attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**2**  CA# 139718

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 07/15/2020

Response: CA COMPLETED

Date of Completion: 07/09/2020

Operator Comment: Erosional channel was from a breach in the irrigational ditch above the well pad. Landowner had repaired the ditch however the erosional channel along the pipeline onto the well pad was not addressed. Rock rundown installed to prevent further erosion over the pipeline. A berm installed to address other potential run onto the pad. see attached photos of work completed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action completed to address erosion created by breach in irrigation ditch above the well pad.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Specialist

Date: 7/27/2020 3:05:08 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402453705	FIR RESOLUTION SUBMITTED
402453710	Erosion work completed
402453712	Weed treatment completion

Total Attach: 3 Files