

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/24/2020

Submitted Date:

10/05/2020

Document Number:

699700194

**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Wilbourn, Don		dwilbourn@bry.com	
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474500	SPILL OR RELEASE	AC	04/27/2020		-	Long Ridge J15	EI

**General Comment:**

On September 24, 2020 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of BERRY PETROLEUM COMPANY LLC (Berry operator #10091) Long Ridge J15 Spill/Release Point ID 474500, Remediation #15535.



**Environmental****Spill/Remediation:**

Comment: See Spill/Release Point ID 474500, Remediation #15535 for more information. Impacted material from the spill/release excavation is currently being landfarmed on the J15 Location (Location ID 335568). The excavation around the pipeline is still present along with a recently installed monitoring well. A cube container adjacent to the monitoring well contained a fluid with two distinct visible layers and a very strong hydrocarbon odor. The monitoring well is constructed with 4-inch PVC and the top of the monitoring well was open at time of inspection.

Corrective Action: Operator shall submit a Supplemental Form 19 requesting closure of Spill/Release Point ID 474500, with work proceeding under an approved Form 27 Remediation #15535. Date: 10/19/2020

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700195	20200924 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262147</a>