

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2020

Submitted Date:

10/07/2020

Document Number:

690200711

**FIELD INSPECTION FORM**

Loc ID 308128 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergyllc.com	
Dylan Thomsen		timothy.thomsen@state.co.us	
BAKER DAVID		dbaker@auroramp.com	
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	
Santistevan, Vince		vincesantistevan@tcenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262543	WELL	PR	07/01/2017	GW	071-07560	APACHE CANYON 10-16V	RI

**General Comment:**

This is a stormwater management inspection. See attached photos and additional details within this report.

Any corrective actions from previous inspection that have not been addressed are still applicable.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is vehicle rutting and road degradation traveling to the location. There is areas where water is not properly diverted causing stormwater to accumulate along the road. There is oil in the engine skid and oil stained soil around the engine skid that needs to be cleaned up. This was also cited in the previous inspection. Operator must perform maintenance of equipment to prevent leaks.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C  
Implement or modify BMPs for improved material handling and spill prevention.  
Immediately clean up area.

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	291908	1881309	
	291908	1881309	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200712	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264087">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264087</a>