

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2020

Submitted Date:

10/09/2020

Document Number:

690200715**FIELD INSPECTION FORM**Loc ID 308687 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279048	WELL	TA	03/11/2014	GW	071-08459	BLAZER 24-1	RI

General Comment:

[This is a location and stormwater management inspection.](#)
[See attached photos and additional details within this report.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well sign posted at meter shed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment and pipe risers at the location.		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 603.f.	Date:	11/13/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: There is areas of erosion along the access road and culverts are filled in with sediment.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/13/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402507768	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266127
690200716	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266118