

FORM
6Rev
02/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402513411

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Valerie Danson

Name of Operator: PDC ENERGY INC

Phone: (970) 506-9272

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-23955-00

Well Name: WALKER

Well Number: 14-10

Location: QtrQtr: SWSW

Section: 10

Township: 6N

Range: 63W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.496239

Longitude: -104.429415

GPS Data: GPS Quality Value: 1.5 Type of GPS Quality Value: PDOP

Date of Measurement: 09/10/2020

GPS Instrument Operator's Name: Devin Arnold

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	6732	6740	09/17/2020	B PLUG CEMENT TOP	6682

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	542	380	542	0	VISU
1ST	7+7/8	4+1/2	10.5	6,919	170	6,919	5,824	CBL
S.C. 1.1				5,824	500	5,824	370	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6682 with 2 sacks cmt on top. CIBP #2: Depth 6402 with 2 sacks cmt on top.
CIBP #3: Depth 2800 with 2 sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 240 ft. with 20 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 130 sacks half in. half out surface casing from 1660 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: 09/17/2020
of _____

*Wireline Contractor: Rocky Mtn Wireline Services

*Cementing Contractor: NexTier Cementing Services

Type of Cement and Additives Used: Class G 15.8 PPG Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Walker 14-10 (05-123-23955)/Plugging Procedure
Producing Formation: Codell: 6732'-6740'
Upper Pierre Aquifer: 560'-1560'
TD: 6929' PBTD: 6860' (4/27/2015)
Surface Casing: 8 5/8" 24# @ 542' w/ 380 sxs cmt
Production Casing: 4 1/2" 10.5# @ 6919' w/ 670 sxs cmt (TOC @ 370' - CBL)

Procedure:

1. MIRU pulling unit. Pull 2 3/8" tubing.
2. RU wireline company.
3. TIH with CIBP. Set BP at 6682'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Codell perfs @ 6732')
4. TIH with CIBP. Set BP at 6402'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Niobrara @ 6452')
5. TIH with CIBP. Set BP at 2800'. Top with 2 sxs 15.8#/gal CI G cement.
6. Run a CBL from 600' to Surface for perf shot verification (log not kept).
7. TIH with perf gun. Shoot squeeze holes @ 240'.
8. TIH with tubing to 1660'. RU cementing company. Mix and pump 130 sxs 15.8#/gal CI G cement down tubing. Cement circulate to surface.
9. Close off casing returns. Hook up cement line to cement flange and pump 20 sxs 15.8#/gal CI G cement downhole and squeeze through perforations @ 240' into annular space. Cement circulate to surface.
10. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Valerie Danson

Title: Reg Tech

Date: _____

Email: valerie.danson@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

<u>COA Type</u>	<u>Description</u>
-----------------	--------------------

--	--

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
--------------------	-------------

402513412	CEMENT JOB SUMMARY
402513413	OPERATIONS SUMMARY
402513414	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>
-------------------	----------------

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)