

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402477387

Date Received:

08/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name             | Phone                 | Email                      |
|--------------------------|-----------------------|----------------------------|
| <u>Shorty, Priscilla</u> |                       | <u>pshorty@hilcorp.com</u> |
| <u>Ray, Mandy</u>        | <u>(505) 599-4083</u> | <u>mray@hilcorp.com</u>    |

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902074

Inspection Date: 07/28/2020

FIR Submit Date: 07/31/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325473

Location Name: ARGENTA-UTE-M34N10W Number: 31NWSE County: LA PLATA

Qtrqr: NWSE Sec: 31 Twp: 34N Range: 10W Meridian: M

Latitude: 37.144130 Longitude: -107.971800

FACILITY - API Number: 05-067- -00 Facility ID: 214838

Facility Name: ARGENTA-UTE (EPA) Number: 3

Qtrqr: NWSE Sec: 31 Twp: 34N Range: 10W Meridian: M

Latitude: 37.144130 Longitude: -107.971800

CORRECTIVE ACTIONS:

1 ☒ CA# 140903

Corrective Action: Control weeds.

Date: 08/15/2020

Response: CA COMPLETED

Date of Completion: 08/26/2020

Operator Comment: all Musk Thistle was removed and hauled off

COGCC Decision: Approved pending re-inspection

|                       |  |
|-----------------------|--|
| COGCC Representative: |  |
| 2                     | <input checked="" type="checkbox"/> CA# 140904   |
| Corrective Action:    | Stormwater controls need to be installed to stabilize erosion within the project area. <span style="float: right;">Date: 08/31/2020</span> |
| Response:             | CA COMPLETED <span style="float: right;">Date of Completion: 08/26/2020</span>   |
| Operator Comment:     | berm built on edge of location to keep bank from eroding.  |
| COGCC Decision:       | Approved pending re-inspection   |
| COGCC Representative: | <div style="border: 1px solid black; height: 40px;"></div>   |

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker Signed: \_\_\_\_\_

Title: Operation/Regulatory Tech Date: 8/28/2020 9:51:42 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>       |
|------------------------|--------------------------|
| 402477387              | FIR RESOLUTION SUBMITTED |
| 402477392              | Resolved Photos          |

Total Attach: 2 Files