

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402510168

Date Received:

10/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 83555

Name of Operator: SUNBURST INC

Address: P.O. BOX 140266

City: EDEGEWATER State: CO Zip: 80214

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Joe Mazotti

Phone

720-226-5791

Email

ogp-co@comcast.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 693700610

Inspection Date: 10/12/2020

FIR Submit Date: 10/12/2020

FIR Status: _____

Inspected Operator Information:

Company Name: SUNBURST INC

Company Number: 83555

Address: P.O. BOX 140266

City: EDEGEWATER State: CO Zip: 80214

LOCATION - Location ID: 331730

Location Name: HENDERSON-67N57W Number: 10SESE County: _____

Qtrqr: SESE Sec: 10 Twp: 7N Range: 57W Meridian: 6

Latitude: 40.583277 Longitude: -103.736461

FACILITY - API Number: 05-123- -00 Facility ID: 331730

Facility Name: HENDERSON-67N57W Number: 10SESE

Qtrqr: SESE Sec: 10 Twp: 7N Range: 57W Meridian: 6

Latitude: 40.583277 Longitude: -103.736461

CORRECTIVE ACTIONS:

1 CA# 142679

Corrective Action: Properly dispose of oily waste in accordance with 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/07/2020

Response: CA COMPLETED

Date of Completion: 10/10/2020

Operator Comment: In accordance with 907.e. Sunburst Inc. has removed the oily waste from the location and disposed the waste at a approved disposal facility and has securely fasten all valves, pipes, and fittings to ensure good mechanical condition.
Sunburst will inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

COGCC Decision: **Not Approved**

COGCC Representative: Fresh road base covering oily waste at northeast crude oil tank. Oil saturated soil remains. See Inspection #693700618

2 ☒ CA# 142680

Corrective Action: Operator shall remove accumulated oil from pit and take immediate action to prevent further accumulation of oil in pit. Submit FIRR with a description of corrective actions taken to treat produced water and prevent oil accumulation in pit. Corrective Action Date is original date from Inspection #696302511

Date: 09/24/2020

Response: CA COMPLETED

Date of Completion: 10/10/2020

Operator Comment: Sunburst will have a crew inspect and make any repairs necessary to the Heater Treater assembly to insure all components and valves are functioning properly. Also, have a hot oil unit clean out and remove any captured remedial oil from the 70 barrel skim pit tank to prevent any further oil from entering the reserve pit.

I've attached the work ticket from Elite Oilfield for the hot oil work done to the skim pit to remove any captured oil and confirming the skim pit was cleaned out. I have the roustabout tickets for the treater work done, too if required. There shouldn't be any oil on the pits now, even though his photos show dark water which is iron sulfate accumulation from our recent workover and stimulation procedure in September.

COGCC Decision: Approved

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joe Mazotti

Signed:

Title: agent

Date: 10/13/2020 8:47:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402510168	FIR RESOLUTION SUBMITTED
402510322	henderson filed ticket

Total Attach: 2 Files