

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402522268

Date Received:

10/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Armstrong, Jon

jarmstrong@bry.com

Kellerby, Shaun

shaun.kellerby@state.co.us

Wilbourn, Don

dwilbourn@bry.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701100616

Inspection Date: 10/20/2020

FIR Submit Date: 10/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BERRY PETROLEUM COMPANY LLC

Company Number: 10091

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

LOCATION - Location ID: 335516

Location Name: SCHOOL HOUSE POINT OM Number: _____ County: _____
A21 696

Qtrqtr: NENE Sec: 21 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.515189 Longitude: -108.105700

FACILITY - API Number: 05-045-

-00

Facility ID: 335516

Facility Name: SCHOOL HOUSE POINT OM Number: _____
A21 696

Qtrqtr: NENE Sec: 21 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.515189 Longitude: -108.105700

CORRECTIVE ACTIONS:

1 ☒ CA# 142831

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 24 hours to fix the leak or isolate leak.

Date: 10/21/2020

Response: CA COMPLETED

Date of Completion: 10/20/2020

Operator Comment: Leak was fixed the next morning after inspection. Operator repacked and greasee sealed the stem of valve and tightened all fittings.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Leak was fixed the next morning after inspection. Operator repacked and greasee sealed the stem of valve and tightened all fittings.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Don Wilbourn

Signed: _____

Title: Production Foreman

Date: 10/29/2020 5:39:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402522268	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files