

# Inspection Photos

11/02/2020

Operator: BERRY PETROLEUM COMPANY LLC

# 10091

Location ID: 335964

Garfield, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC # 10091

Location ID: 335964



**Photo 1:** Photo taken from the western interim areas of the location, facing south. Photo shows noxious weeds remaining on the Location. Previous inspections observed seed dispersal in process. It was observed in this inspection that seed dispersal appears to have been allowed to be completed, as the majority of the weed's seed heads are now bare. Weeds have not been removed as indicated by the FIRR; Unable to find evidence that sufficient weed management activities to prevent establishment and spread of noxious weeds on and from the Location have been conducted.



**Photo 2:** Photo shows weed with bare seed head. Weed seed can be observed at the base of the plant, as well as an additional rosette. See comments under photo 1.



## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC # 10091

Location ID: 335964



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC # 10091

Location ID: 335964



**Photo 5:** Photo taken from the western interim areas of the location, facing north. Photo shows noxious weeds remaining on the Location. Previous inspections observed seed dispersal in process. It was observed in this inspection that seed dispersal appears to have been allowed to be completed, as the majority of the weed's seed heads are now bare. Weeds have not been removed as indicated by the FIRR; Unable to find evidence that sufficient weed management activities to prevent establishment and spread of noxious weeds on and from the Location have been conducted.



**Photo 6:** See comments under photo 5.