

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402536881

Date Received:

11/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10720

Name of Operator: KODA EXPLORATION LLC

Address: 2443 SOUTH UNIVERSITY BLVD 215

City: DENVER State: CO Zip: 80210

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>ELGERD ANDERS</u>		<u>elgerd@comcast.net</u>
<u>JOSEPH RESENDEZ</u>		<u>rezenjp@gmail.com</u>
<u>SULLIVAN RYAN</u>		<u>rsullivanvc@gmail.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200798

Inspection Date: 11/05/2020

FIR Submit Date: 11/09/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KODA EXPLORATION LLC

Company Number: 10720

Address: 2443 SOUTH UNIVERSITY BLVD 215

City: DENVER State: CO Zip: 80210

LOCATION - Location ID: 477611

Location Name: WHP Misty Number: 2-7 Pad County: LINCOLN

Qtrqtr: NWNE Sec: 7 Twp: 17S Range: 54W Meridian: 6

Latitude: 38.593580 Longitude: -103.492650

FACILITY - API Number: 05-073-00 Facility ID: 477612

Facility Name: WHP Misty Number: 2-7

Qtrqtr: NWNE Sec: 7 Twp: 17S Range: 54W Meridian: 6

Latitude: 38.593580 Longitude: -103.492650

CORRECTIVE ACTION:

1 CA# 144253

Corrective Action: Comply with 1002.c

Date: _____

Response: CA COMPLETED

Date of Completion: 11/19/2020

Operator Comment: Hydromulch with tackifier was applied to stockpiled topsoil to stabilize and as a best management practice to protect from degradation due to wind and water erosion in compliance with rule 1002.c (Photographs attached).

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Hydromulch with tackifier was applied to stockpiled topsoil to stabilize and as a best management practice to protect from degradation due to wind and water erosion in compliance with rule 1002.c (Photographs attached).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Del Hierro

Signed: _____

Title: Agent

Date: 11/19/2020 6:51:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402536882	View of topsoil stabilization from pad entrance facing southwest
402536883	View of topsoil stabilization from pad entrance facing northeast
402536884	View of topsoil stabilization from northwest corner of pad facing northeast
402536885	View of topsoil stabilization from southeast corner of pad facing southwest
402536886	View of topsoil stabilization from southwest corner of pad facing southeast

Total Attach: 5 Files