

FORM

6

Rev
11/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE

ET

OE

ES

Document Number:

402538539

Date Received:

11/23/2020

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 44180

Contact Name: Kenneth Rennick

Name of Operator: J R OIL COMPANY

Phone: (970) 8783846

Address: BOX 1707

Fax:

City: GUNNISON State: CO Zip: 81230

Email: krennick@blm.gov

For "Intent" 24 hour notice required,

Name: Waldron, Emily

Tel: (970) 819-9609

COGCC contact:

Email: emily.waldron@state.co.us

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-081-05265-00

Well Name: MIDWEST GOVT (OWP)

Well Number: 1

Location: QtrQtr: NWSE Section: 29 Township: 5N Range: 91W Meridian: 6

County: MOFFAT

Federal, Indian or State Lease Number: 38057

Field Name: MOFFAT

Field Number: 55700


Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.352639

Longitude: -107.626558

GPS Data: GPS Quality Value: 9.0 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 11/23/2020

Reason for Abandonment:


☐ Other

Casing to be pulled:



Estimated Depth:

Fish in Hole:



If yes, explain details below

Wellbore has Uncemented Casing leaks:



If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	2804	3229	10/07/2020	CEMENT	2681

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	20	10+3/4	NA	32.75	0	163	75	163	0	CALC
1ST	20	7	NA	NA	0	2804	50	2804	2400	CALC
OPEN HOLE	6+1/4				2804	3229				

Subsurface hazards include, but are not limited to, the following: overpressured zones, underpressured zones, major geologic faults, salt sections, H₂S at concentrations greater than or equal to 100 ppm.

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 80 sks cmt from 3078 ft. to 2681 ft. Plug Type: OPEN HOLE Plug Tagged: ☒
 Set 50 sks cmt from 2675 ft. to 2389 ft. Plug Type: CASING Plug Tagged: ☒
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 220 ft. with 208 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 108 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 10/10/2020 Cut and Cap Date: 10/10/2020 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 0

*Wireline Contractor: Alliance Energy Services

*Cementing Contractor: Alliance Energy Services

Type of Cement and Additives Used: Class G 15.8 lb/gal 1.15 ft³/sk

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Form filed for the BLM by COGCC

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Aaron Katz

Title: NW Area Engineer Date: 11/23/2020 Email: aaron.katz@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Katz, Aaron Date: 11/23/2020

CONDITIONS OF APPROVAL, IF ANY:

<u>COA Type</u>	<u>Description</u>

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402538539	FORM 6 SUBSEQUENT SUBMITTED
402538597	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Well plugged by the BLM as part of the federal OWP GPS quality value and date are unknown due to OWP status-place holder values entered Hole size is unknown, entered 20" to meet form IT rules Well plugged prior to new WBI rules effective date-no wait period for cut and cap required No production data on file, attempts were made to recieve production reporting data with no success, scout card has been updated to PA Location did not match coordinates, updated with lat/long from BLM	11/23/2020

Total: 1 comment(s)