

Inspection Photos

11/19/2020

Operator: SG INTERESTS I LTD # 77330

Location ID: 422990

Gunnison, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 422990



Photo 1: Photo taken from the northwest end of the Location, facing northeast. Photos 1-3 provide an overview of the Location from northeast, south to southwest.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 422990



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the location entrance. Photo shows signage has been installed per COAs from Form 4 #402247341

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 422990



Photo 5: Photo taken from the ditch on the northeastern end of the Location. Previous inspections observed Canada thistle within ditch and required Operator to conduct weed management. Due to the onset of winter conditions and plant dormancy, it is unclear if sufficient weed management activities have been conducted. A followup inspection will need to be conducted during the 2021 growing season to determine compliance with Rule 1003.f



Photo 6: Photo taken from the cut slopes on the northeast end of the Location, facing southwest. Photo shows BMPs to protect and stabilize the slopes remaining missing or insufficient.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 422990



Photo 7: Photo taken from the cut slopes on the northeast end of the Location, facing southwest. Photo shows BMPs to protect and stabilize the slopes remaining missing or insufficient.



Photo 8: Photo taken from the cut slopes on the northeast end of the Location, facing northeast. Photo shows BMPs to protect and stabilize the slopes remaining missing or insufficient.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 422990



Photo 9: Photo taken from the cut slopes on the northeast end of the Location, facing east. Photo shows BMPs to protect and stabilize the slopes remaining missing or insufficient.



Photo 10: Photo taken from the cut slopes on the northeast end of the Location, facing northeast. Photo shows BMPs to protect and stabilize the slopes remaining missing or insufficient.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 422990



Photo 11: Photo taken from the cut slopes on the northeast end of the Location. Photo shows erosion is beginning to recur.

