

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2020

Submitted Date:

12/02/2020

Document Number:

700900362**FIELD INSPECTION FORM**Loc ID 320461 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10711Name of Operator: PAINTED PEGASUS PETROLEUM LLCAddress: 16820 BARKER SPRINGS RD #521City: HOUSTON State: TX Zip: 77084**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Frank Bair		fbair@p3petro.com	
Joey Mustacchia		jmustacchia@p3petro.com	
KEITH HUBBARD		khubbard@P3Petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203821	WELL	SI	12/01/2019	GW	001-09381	VERNON GRADY 12-20	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Dead Weeds, trash and debris.		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date 12/18/2020. See attached photos #1 through #7.	Date:	12/18/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	RTU		
Corrective Action:		Date:	
Type: Vertical Heated Separator	#		
Comment:	Stained soil around separator.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 12/30/2020 to remove stained soil. See attached photo #8.	Date:	12/30/2020
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		39.864421,-104.244266	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Inadequate berms around tank(s) / separator(s).				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 12/30/2020. See attached photos #5 & #6.				Date: 12/30/2020

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203821 Type: WELL API Number: 001-09381 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday November 13, 2020 at approximately 10:30am, I, Inspector Chane Finkenbinder, conducted an on-site inspection at Vernon Grady, Painted Pegasus Petroleum, at API #001-09381 in Adams County Colorado.</p> <p>While there, I observed a Shut in well,</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Dead Weeds, trash and debris. Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P. Corrective Action Date 12/18/2020. See attached photos #1 through #7.</p> <p>Inadequate berms around tank(s) / separator(s) Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 12/30/2020. See attached photos #5 & #6.</p> <p>Stained soil around separator. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 12/30/2020 to remove stained soil. See attached photo #8.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	12/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402545079	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301790
700900363	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301787