

GOLDEN EAGLE 21-15X API# 05-071-08063 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 07, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200656



PHOTO 1: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE MAIN ROAD IN LOPEZ CANYON.

GOLDEN EAGLE 21-15X API# 05-071-08063 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 07, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200656



PHOTO 2: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE MAIN ROAD IN LOPEZ CANYON.

GOLDEN EAGLE 21-15X API# 05-071-08063 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 07, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200656



PHOTO 3: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE MAIN ROAD IN LOPEZ CANYON.

GOLDEN EAGLE 21-15X API# 05-071-08063 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 07, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200656



PHOTO 4: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE MAIN ROAD IN LOPEZ CANYON.

GOLDEN EAGLE 21-15X API# 05-071-08063 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 07, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200656



PHOTO 5: THE EROSION IN THE BAR DITCH WAS BACK FILLED AND COMPACTED WITH THE TIRE ON THE BACKHOE.



GOLDEN EAGLE 21-15X API# 05-071-08063 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: DECEMBER 07, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200656



PHOTO 6: THE EROSION IN THE BAR DITCH WAS BACK FILLED AND COMPACTED WITH THE TIRE ON THE BACKHOE.