

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335889

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 1: Photo taken from the north end of the Location, facing northwest. Operator applied mulch to the slopes; BMP insufficient to stabilize/protect slopes and/or has not been installed on slope in accordance with good engineering practices.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 2: Photo taken from the north end of the Location, facing northwest. Operator applied mulch to the slopes; BMP insufficient to stabilize/protect slopes and/or has not been installed on slope in accordance with good engineering practices.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 3: Photo taken from the north end of the Location, facing west. Operator applied mulch to the slopes; BMP insufficient to stabilize/protect slopes and/or has not been installed on slope in accordance with good engineering practices.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 4: Photo taken from the north end of the Location, facing west. Operator applied mulch to the slopes; BMP insufficient to stabilize/protect slopes and/or has not been installed on slope in accordance with good engineering practices.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 5: Photo taken from the north end of the Location, facing north. Photo shows areas of cut slope on the north end of the Location where BMPs have not been implemented to stabilize or protect cutslopes. .



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335889



Photo 6: Photo taken from the north end of the Location, facing north. Photo shows areas of cut slope on the north end of the Location where BMPs have not been implemented to stabilize or protect cutslopes.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335889



Photo 7: Photo taken from the north end of the Location, facing west. Operator applied mulch to the slopes; BMP insufficient to stabilize/protect slopes and/or has not been installed on slope in accordance with good engineering practices.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources