

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2020

Submitted Date:

12/22/2020

Document Number:

690102221**FIELD INSPECTION FORM**Loc ID 327542 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hamilton, Greg		Gregory_Hamilton@oxy.com	
Gintautas, Peter		peter.gintautas@state.co.us	
		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478862	SPILL OR RELEASE	CL	12/18/2020		-	Webber 11-4	EG

General Comment:

Engineering Integrity inspection performed on December 21st, 2020 in response to initial form 19 spill report Doc #402554501 received by COGCC on 12/18/2020 that outlines: A hole in a production tank at the Webber 11-4 facility resulted in the release of less than 3 barrels of oil inside a lined steel containment berm. Following the removal of the above-ground storage tanks and the partially buried produced water vessel, the petroleum hydrocarbon impacted soil was removed down to the liner, and the liner was washed.

Details of observations made during this field inspection are located in the equipment/ tanks and comment sections of report.
Photos uploaded.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	(4) wells, flowlines and equipment are SI; Tank repair/ replacement work in progress. (3) tanks have been removed from lined secondary containment. (2) tanks were observed east of and adjacent to metal tank berm; (1) 300 bbl steel AST crude oil tank and (1) 200 bbl fiberglass PBV produced water tank. The failed tank (300 bbl AST) appears to have been removed from location. The cause of failure resulting in the release is unknown at this time. No Oxy or contract personnel were on location at time of inspection.					
Corrective Action:					Date:	

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 478862 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

COGCC Comments

Comment	User	Date
<p>As outlined in the CA section of COGCC form 19 doc #402554501; A hole in a production tank at the Webber 11-4 facility resulted in the release of less than 3 barrels of oil inside a lined steel containment berm. The produced water vessel will be replaced.</p> <p>Note: Document/ detail the root cause of failure, accurate description of the tank that failed/ being replaced and measures taken to prevent a recurrence (in CA section of the COGCC supplemental form 19).</p>	maclarej	12/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102224	Signage; view of tank berm area (tanks removed)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5315174
690102225	Tanks removed from berm area; PW/ CO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5315175
690102226	View of location (soils stockpiles); to east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5315176