

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402531350

Date Received:  
11/12/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Knudson, Dwayne</u>	<u>970-456-3335</u>	<u>dknudson@ursaresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402599

Inspection Date: 10/16/2020 FIR Submit Date: 11/02/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC Company Number: 10447

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 418417

Location Name: Porter Number: B Pad County: \_\_\_\_\_

Qtrqr: SWS Sec: 17 Twp: 6S Range: 90W Meridian: 6  
W

Latitude: 39.521841 Longitude: -107.472668

FACILITY - API Number: 05-045-00 Facility ID: 418417

Facility Name: Porter Number: B Pad

Qtrqr: SWS Sec: 17 Twp: 6S Range: 90W Meridian: 6  
W

Latitude: 39.521841 Longitude: -107.472668

CORRECTIVE ACTIONS:

1  CA# 144073

Corrective Action: Revegetate failed areas of Fill slope; providing stabilization of disturbed areas until vegetation establishes. Reclamation activities should be complete by 11/30/20, or if weather delays, Spring 2021 as soon as weather and soil conditions permit.

Date: 11/30/2020

Response: CA COMPLETED Date of Completion: 11/11/2020

Operator Comment: Seed was reinstalled and covered with erosion control blankets by landowners. See photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

2  CA# 144074

Corrective Action: Install or repair required BMPs per Rule 1002.f.; providing long term stabilization of slopes. CA Date is 11/30/20, or if weather delays, Spring 2021 as soon as weather and soil conditions permit.

Date: 11/30/2020

Response: CA COMPLETED

Date of Completion: 11/11/2020

Operator Comment: Erosion was addressed and seed was reinstalled and covered with erosion control blankets by landowners. See photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Please send to Lou Colby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed: \_\_\_\_\_

Title: Environmental Manager

Date: 11/12/2020 11:51:03 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402531350	FIR RESOLUTION SUBMITTED
402531351	Repair Photos

Total Attach: 2 Files