

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2021

Submitted Date:

01/11/2021

Document Number:

696202201

FIELD INSPECTION FORM

Loc ID 312560 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 34720
Name of Operator: GORDON ENGINEERING INC
Address: PO BOX 3525
City: GRAND JUNCTION State: CO Zip: 81502

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		johngordon1gordon@yahoo.com	
		Parks.Barroso@coag.gov	
Arthur, Denise		denise.arthur@state.co.us	
		Scott.Schultz@coag.gov	
		travis.gordon.usmc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221906	WELL	PA	02/01/2017	GW	077-08508	FEDERAL 32-2	RI
312560	LOCATION	CL			-	FEDERAL-69S97W 32NWSE	RI

General Comment:

On 1/8/2021, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Gordon Engineering Inc's Federal 32-2 location in Mesa County, Colorado.

This inspection is a follow up to #696201937 to document compliance with the following corrective actions:

311.b: Subsequent Report of Abandonment

1003.f: Stormwater

1004.a: Final Reclamation

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

Refer to the "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 221906 Type: WELL API Number: 077-08508 Status: PA Insp. Status: RI

Workover

Comment: Inspection #696201937 documented that no Subsequent Form 6, and plugging records have been submitted by Operator. Inspection required Operator to comply with Rule 311.b and submit the Form 6 - Subsequent Report of Abandonment by 11/5/2020.

Operator submitted Form 6(s) #402523427 (Received 10/30/2020). This corrective action has been addressed.

Corrective Action:

Date:

Facility ID: 312560 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Inspection #696201937 documented that final reclamation activities have not been commenced including, but not limited to, compaction alleviation (cross ripping to a minimum depth of 18 inches), contouring/regrading, replacement of soils and revegetation activities on the Location and access road. Inspection required Operator to comply with 1004 rules by 11/30/2020.

It was observed in this inspection that final reclamation activities have not been completed in accordance with COGCC 1004 Rules and corrective actions; Original corrective action and date remains applicable.

Corrective Action: **Complete final reclamation activities pursuant to 1004 Rules including, but not limited to, compaction alleviation, contouring/regrading, replacement of soils and revegetation activities on the Location and access road.**

Date **11/30/2020**

Overall Final Reclamation **Fail** Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696201937 documented that cement waste was spilled onto approximately 0.11 acres of the surface north of the Location in violation of Rule 1002.f.(2)B. Inspection required Operator to clean or remove impacted soils by 11/30/2020.

Due to limited visibility from snow cover, Reclamation Specialist was unable to accurately determine if the corrective action has been addressed; no resolution documentation or records have been submitted by the Operator to show that the corrective action has been addressed, therefore the original corrective action and date will remain applicable; A followup inspection will be conducted to determine compliance with COGCC Stormwater Rules.

Corrective Action: **Clean or Remove impacted soils by 11/30/2020.**

Date: 11/30/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402571922	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327072
696202202	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327057