

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402577236

Date Received:

01/18/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

Sabre.Beebe@bp.com

—

SanJuanCOGCC@bp.com

SJN Inspection general email

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601600

Inspection Date: 05/05/2017

FIR Submit Date: 06/05/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325501

Location Name: SHOEMAKER-N35N8W Number: 34NWSE County: LA PLATA

Qtrqr: NWSE Sec: 34 Twp: 35N Range: 8W Meridian: N

Latitude: 37.255727 Longitude: -107.728732

FACILITY - API Number: 05-067- -00 Facility ID: 214901

Facility Name: SHOEMAKER Number: 01-34 1

Qtrqr: NWSE Sec: 34 Twp: 35N Range: 8W Meridian: N

Latitude: 37.255727 Longitude: -107.728732

CORRECTIVE ACTIONS:

1 CA# 80339

Corrective Action: Remove debris and equipment or provide a signed surface owner waiver (in accordance with recent guidance document "Rule 1001.c: Reclamation Waivers and Variances") accepting responsibility for materials stored on the well pad. This letter should define areas on the well pad where surface owner equipment will be stored.

Date: 08/31/2017

Response: CA COMPLETED

Date of Completion: 01/12/2021

Operator Comment: Operations visited location and verified landowner belongings have been removed from location.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 80340

Corrective Action: Repair northern diversion and apply stormwater controls to de-energize flows and reduce sediment flows.

Date: 07/07/2017

Response: CA COMPLETED

Date of Completion: 07/17/2017

Operator Comment: Storm water BMP repairs have been performed on location. Repairs have been made to erosion channels, repairs have been made to the location berm and wattles have been installed to prevent sediment flow and to slow down storm waters. See attached documentation. FIRR 401343346 filed 7/17/2017

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions completed. Please see attached document.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 1/18/2021 10:20:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402577255	Work completion photos
-----------	------------------------

Total Attach: 1 Files