

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402577263

Date Received:
01/18/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SJN Inspection general email

sjninspections@ikavenergy.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902169

Inspection Date: 08/20/2020

FIR Submit Date: 08/21/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 312068

Location Name: BONDAD 33-9-N33N9W Number: 6NESW County: LA PLATA

Qtrqr: NESW Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129634 Longitude: -107.870406

FACILITY - API Number: 05-067-00 Facility ID: 267414

Facility Name: CLOVIS A Number: 2

Qtrqr: NESW Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129634 Longitude: -107.870406

CORRECTIVE ACTIONS:

1 CA# 141411

Corrective Action:

Date: 09/30/2020

Stormwater and erosion controls installed in response to 2018 reclamation inspection are not adequate. Long-term stormwater controls and erosion controls including slope stabilization measures, need to be installed to stabilize erosion within the project area. Stormwater and erosion controls need to be selected, sized, installed, and maintained according to good engineering practices. Erosion controls need to be maintained in place until bare and weedy soils on slopes are stabilized with desirable perennial vegetation. As response to 2018 corrective action is noted, a new corrective action date is assigned. This is the second corrective action for stormwater erosion at this location.

Response: CA COMPLETED

Date of Completion: 01/15/2021

Operator Comment: Equipment moved to accommodate for the fill dirt on the southwest corner to be placed in the cut slope to obtain a better slope for vegetation establishment. Performed recontour as near as practical on active well pad, seeded cut and fill, mulched fill area and installed 100% ECB on the cut sloper. See attached documentation.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Action completed see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 1/18/2021 10:30:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402577273	Work completion documentation
-----------	-------------------------------

Total Attach: 1 Files