

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402587750

Date Received:
02/01/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>		<u>spwu@chevron.com</u>
<u>Sandford, Anita</u>		<u>ATLX@chevron.com</u>
<u>Olson, Andrew</u>		<u>andrewolson@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202214

Inspection Date: 01/19/2021

FIR Submit Date: 01/20/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 397204

Location Name: S H MCLAUGHLIN-62N102W Number: 32SENE County: _____

Qtrqtr: SENE Sec: 32 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101286 Longitude: -108.860065

FACILITY - API Number: 05-103-00 Facility ID: 397204

Facility Name: S H MCLAUGHLIN-62N102W Number: 32SENE

Qtrqtr: SENE Sec: 32 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101286 Longitude: -108.860065

CORRECTIVE ACTIONS:

1 CA# 145998

Corrective Action: Comply with 1004 rules.

Date: 04/15/2021

Response: CA COMPLETED

Date of Completion: 01/29/2021

Operator Comment: Concrete debris, various pipe and anchor equipment was removed. See Attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

Corrective action required Operator to "comply with 1004 rules". Photo documentation shows additional surface disturbance during work, areas will require reclamation. If it is determined that work has not been conducted to revegetate/reclaim the disturbances, then the original CA and date will remain applicable.

A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Concrete debris, various pipe and anchor equipment was removed. See Attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: _____

Title: Lead Safety Specialist

Date: 2/1/2021 10:45:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402587750	FIR RESOLUTION SUBMITTED
402587768	Area Photo
402587783	Area Photo

Total Attach: 3 Files