

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Rutting on location around separator and tank battery.



**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Rutting on location around separator and tank battery.



Rutting on location around separator and tank battery.



**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWE
Location # 323884**



Rutting on location around separator and tank battery.



Rutting on location around well head.

TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884



Rutting on location around well head.



Rutting on location around well head.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Road ditch needs maintained.



**Culvert on access road. Coordinates
39.471159 -108.074028**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWE
Location # 323884**



Culvert is damaged in ditch.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



**No tracking bmps observed at access road
and CR215.**



**Mud hole from impoundment of storm
water.**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Tracking of sediment at access rd. and CR 215.



Tracking of sediment at access rd. and CR 215.