

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



Location shows signs of lack of stabilization BMP's in some areas (rutting is present).



Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



Culvert basin needs maintained.



BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



Water not draining off road.



N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597



**N39.55348 W-108.11985 Erosion damage from
culvert outlet.**



Erosion has exposed pipe line.

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location ID: 335597

