

FORM

6

Rev  
11/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE

ET

OE

ES

Document Number:

402553175

Date Received:

12/14/2020

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: CANDICE BARBER

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Phone: (307) 233-4513

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: CANDICE\_BARBER@OXY.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-34026-00

Well Name: GREEN USX

Well Number: XX07-07D

Location: QtrQtr: SENE Section: 7 Township: 1N Range: 65W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750


## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.069482

Longitude: -104.700921

GPS Data: GPS Quality Value: 2.4 Type of GPS Quality Value: PDOP Date of Measurement: 12/01/2020

Reason for Abandonment:


☐ Other

Casing to be pulled:



Estimated Depth:

Fish in Hole:



If yes, explain details below

Wellbore has Uncemented Casing leaks:



If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7542	7552	09/15/2020	B PLUG CEMENT TOP	7250
NIOBRARA	7316	7403	09/15/2020	B PLUG CEMENT TOP	7250
J SAND	7983	8019	09/15/2020	B PLUG CEMENT TOP	7900
DAKOTA	8185	8260	09/15/2020	B PLUG CEMENT TOP	8090

Total: 4 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24		1161	440	1161	0	VISU
1ST	7+7/8	4+1/2	M80	11.6		8397	208	8397	6360	CBL
	7+7/8	4+1/2		Stage Tool		6286	527	6266	1350	CBL

### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 8090 with 2 sacks cmt on top. CIPB #2: Depth 7900 with 2 sacks cmt on top.  
CIBP #3: Depth 7250 with 2 sacks cmt on top. CIPB #4: Depth 6200 with 2 sacks cmt on top.  
CIBP #5: Depth 4426 with 2 sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 30 sks cmt from 60 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☐  
Set        sks cmt from        ft. to        ft. Plug Type:        Plug Tagged: ☐  
Set        sks cmt from        ft. to        ft. Plug Type:        Plug Tagged: ☐  
Set        sks cmt from        ft. to        ft. Plug Type:        Plug Tagged: ☐  
Set        sks cmt from        ft. to        ft. Plug Type:        Plug Tagged: ☐

Perforate and squeeze at 2000 ft. with 162 sacks. Leave at least 100 ft. in casing 1655 CICR Depth  
Perforate and squeeze at        ft. with        sacks. Leave at least 100 ft. in casing        CICR Depth  
Perforate and squeeze at        ft. with        sacks. Leave at least 100 ft. in casing        CICR Depth

(Cast Iron Cement Retainer Depth)

Set 247 sacks half in. half out surface casing from 1452 ft. to 740 ft. Plug Tagged: ☒

Set        sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set        sacks in rat hole Set        sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1440 ft. of 4+1/2 inch casing

Number of Days from Setting Surface Plug to Capping or Sealing the Well: 0

Surface Plug Setting Date: 12/01/2020 Cut and Cap Date: 12/01/2020

\*Wireline Contractor: CUTTERS

\*Cementing Contractor: SCHLUMBERGER

Type of Cement and Additives Used:       

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:       

Print Name: CANDICE BARBER

Title: REGULATORY ANALYST

Date: 12/14/2020

Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric

Date: 3/9/2021

CONDITIONS OF APPROVAL, IF ANY:

<u>COA Type</u>	<u>Description</u>

### Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402553175	FORM 6 SUBSEQUENT SUBMITTED
402553201	OTHER
402553203	CEMENT JOB SUMMARY
402553205	WELLBORE DIAGRAM
402553206	WIRELINE JOB SUMMARY
402553207	OPERATIONS SUMMARY
402553225	OTHER
402553228	OTHER

Total Attach: 8 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)