

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2021

Submitted Date:

03/12/2021

Document Number:

690201265

**FIELD INSPECTION FORM**

Loc ID 307278 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		efitzgerald@ogrisop.com	
		timothy.thomsen@state.co.us	
		rmack@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217352	WELL	PR	09/12/2012	GW	071-06128	APACHE CANYON 12-14	RI

**General Comment:**

This is a follow up of the previous stormwater management inspections number 690200600, 690200709, 690200848. See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are culverts along the main road in the canyon that need to be repaired and maintained. Additional BMP's are needed along the steep grade of the road side. There is vehicle rutting occurring on the road ascending to the location. The road needs to be maintained to prevent erosion. Areas of rutting need to be stabilized with gravel and compaction. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/18/2020

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	258528	881802	
	258528	881802	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201266	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374844</a>