

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Plunger Lift	# 1				
Flow Line	# 1				
Other	# 1	Wellbore is secured with a loose fitting metal cover that does not allow for pressure monitoring. See attached photo.	Comply with Rule 434.a.(5).	03/26/2021	
Bradenhead	# 1	Bradenhead valve is exposed at surface.			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Tank battery #443959				
Corrective Action:				Date:	

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 287597 Type: WELL API Number: 123-24376 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 3/12/2021 at approximately 08:55 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Frank 20-31 location #306294 in Weld County, Colorado. While there, I observed that the wellbore is secured with a loose fitting metal cover that does not allow for pressure monitoring. During this inspection the following possible compliance issues were observed: Rule 434.a.(5). with a corrective action date of 3/26/2021. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	03/12/2021

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402627146	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374974
697003287	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374972