

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2021

Submitted Date:

03/23/2021

Document Number:

699103276

FIELD INSPECTION FORM

Loc ID 429920 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacr.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
Grippin, Wyatt	720-415-9544	wgrippin@bonanzacr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429919	WELL	PR	11/01/2019	OW	123-35968	North Platte P-T-34HZ	PR

General Comment:

[New CA's found on 3/23/21](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	Trash in multiple locations, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	<u>04/02/2021</u>
Type	OTHER		
Comment:	Oily Waste in bucket next to compressor, needs to be removed for good housekeeping		
Corrective Action:	Comply with Rule 606.	Date:	<u>04/02/2021</u>
Type	OTHER		
Comment:	Appear to have multiple leaking valves/ fittings fix or replace. See attached photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	<u>04/02/2021</u>
Type	OTHER		
Comment:	Stained soil in several locations needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	<u>04/02/2021</u>
Type	OTHER		
Comment:	Netting is open. See attached photo.		
Corrective Action:	Repair wildlife protection equipment	Date:	<u>04/02/2021</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 429919 Type: WELL API Number: 123-35968 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Well needs updated annual bradenhead test on file. Submit reports per Rule 207.
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 3/23/21 at approximately 1146hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte P-T-34HZ Pad of Bonanza Creek Energy, at Location ID # 429920 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Appear to have multiple leaking valves/ fittings. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 4/2/21. Trash in multiple locations, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 4/2/21. Netting is open. Repair wildlife protection equipment. With a corrective action date of 3/12/21. Stained soil in several locations needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 4/2/21. Oily Waste in bucket next to compressor, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 4/2/21. Well needs updated annual bradenhead test on file. Submit reports per Rule 207. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	03/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402637497	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384316
699103277	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384313