

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402647613

Date Received:
04/02/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ingve, Ed</u>	<u>(303) 680-4725</u>	<u>ed@renegadeoilandgas.com</u>
<u>Chesson, Bob</u>		<u>robert.chesson@state.co.us</u>
<u>Condill, J.B.</u>	<u>(303) 680-4725</u>	<u>jbcrog@aol.com</u>
<u>Espinosa, Bill</u>	<u>(303) 829-4982</u>	<u>billespinosa30@yahoo.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688301208
Inspection Date: 02/15/2018 FIR Submit Date: 02/19/2018 FIR Status: _____

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 322152

Location Name: MORRIS-66S63W Number: 24NWSW County: ELBERT
Qtrqr: NWS Sec: 24 Twp: 6S Range: 63W Meridian: 6
W
Latitude: 39.511370 Longitude: -104.401630

FACILITY - API Number: 05-039-00 Facility ID: 209364

Facility Name: MORRIS Number: 24-12
Qtrqr: NWS Sec: 24 Twp: 6S Range: 63W Meridian: 6
W
Latitude: 39.511370 Longitude: -104.401630

CORRECTIVE ACTIONS:

1 CA# 114503

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e. Contact area COGCC EPS.

Date: 02/22/2018

Response: CA COMPLETED

Date of Completion: 04/01/2018

Operator Comment: Stained soil cleaned up. Wellhead stuffing box mess cleaned up. Engine lube oil leaks cleaned up. Engine replaced with a rebuilt engine.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 114504

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 03/12/2018

Response: CA COMPLETED

Date of Completion: 04/01/2018

Operator Comment: Lube oil containment installed.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: FIR resolution form was not filed after corrective action items were performed. Operator guessed on the corrective action timing but knows the work was performed at that approximate time. FIR is being filed now as a result of a unresolved field inspection report recently run on Renegade leases and at the request of COGCC inspector Susan Sherman. It is hoped that this will be able to clear this issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: _____

Title: Manager/Owner

Date: 4/2/2021 2:47:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files