

TEP ROCKY MOUNTAIN LLC
GV 26-28
Location # 335071



Battery sing is at separators not at tank battery.

TEP ROCKY MOUNTAIN LLC
GV 26-28
Location # 335071



Gaps in fencing.



Gaps in fencing.

TEP ROCKY MOUNTAIN LLC
GV 26-28
Location # 335071



Well fencing has been repaired.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources