

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Battery sign missing information per Rule 605.e.



Battery sign at separator not tank battery.

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Capacity numbers are illegible. The 3s are illegible

Capacity numbers are illegible. The 3s are illegible

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Land farm on location.



Land farm on location.

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Divots in berm.



Divots in berm.

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Berm along west edge of location is damaged from traffic rutting.



Berm along west edge of location is damaged from traffic rutting.

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Ditch along west edge of location is clogged sediment trapped by vegetation growing in south west corner of location.



Ditch along west edge of location is clogged sediment trapped by vegetation growing in south west corner of location.

TEP ROCKY MOUNTAIN LLC
PA 13-32
Location # 335311



Battery sign at separator not tank battery.

Fencing partially down around separator.