

FORM
6Rev
11/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402652267

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Valerie Danson

Name of Operator: PDC ENERGY INC

Phone: (970) 506-9272

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-20207-00

Well Name: KREPS

Well Number: 21-7

Location: QtrQtr: NENW

Section: 7

Township: 6N

Range: 64W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.506140

Longitude: -104.595670

GPS Data: GPS Quality Value: 5.4

Type of GPS Quality Value:

Date of Measurement: 03/15/2007

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7057	7067	02/12/2021	B PLUG CEMENT TOP	7007

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24	0	408	285	408	0	VISU
1ST	7+7/8	4+1/2	J55	10.5	0	7265	150	7265	6200	CBL
S.C. 1.1						6200	200	6200	3190	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7007 with 2 sacks cmt on top. CIBP #2: Depth 6671 with 2 sacks cmt on top.
CIBP #3: Depth 3665 with 2 sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 100 sks cmt from 2550 ft. to 2300 ft. Plug Type: STUB PLUG Plug Tagged: ☐
Set 100 sks cmt from 1630 ft. to 1430 ft. Plug Type: OPEN HOLE Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 285 sacks half in. half out surface casing from 608 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 2500 ft. of 4+1/2 inch casing

Surface Plug Setting Date: 02/15/2021 Cut and Cap Date: 02/23/2021 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 8

*Wireline Contractor: Rocky Mtn Wireline Services

*Cementing Contractor: DUCO Inc. Cementing Services

Type of Cement and Additives Used: Class G 15.8 PPG Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Kreps 21-7 (05-123-20207)/Plugging Procedure
Producing Formation: Codell: 7057'-7067'
Upper Pierre Aquifer: 500'-1530'
TD: 7275' PBTD: 7153' (1/28/2010)
Surface Casing: 8 5/8" 24# @ 408' w/ 285 sxs cmt
Production Casing: 4 1/2" 10.5# @ 7265' w/ 350 sxs cmt (TOC @ 3190' - CBL)

Procedure:

1. MIRU pulling unit. Pull 2 3/8" tubing.
2. RU wireline company.
3. TIH with CIBP. Set BP at 7007'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Codell perms @ 7057')
4. TIH with CIBP. Set BP at 6671'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Niobrara @ 6721')
5. Ran a Strip Log from 2800' to Surface (for casing cut verification, log not kept).
6. TIH with CIBP. Set BP at 3665'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Parkman @ 3715')
7. TIH with casing cutter. Cut 4 1/2" casing @ 2500'. Pull cut casing.
8. TIH with tubing to 2550'. RU cementing company. Mix and pump 100 sxs 15.8#/gal CI G cement down tubing. (Stub plug from 2550'-2300') TOC at 2300'.
9. Wait a sufficient time to confirm static conditions. If at any time after placing this plug there is evidence of pressure or fluid migration, contact engineering before continuing operations
10. TIH with tubing to 1630'. Mix and pump 100 sxs 15.8#/gal CI G cement down tubing. (Pierre coverage from 1630'-1430') TOC at 1430'.
11. Pick up tubing to 608'. Mix and pump 285 sxs 15.8#/gal CI G cement down tubing. Cement circulate to surface.
12. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Valerie Danson
Title: Reg Tech Date: _____ Email: valerie.danson@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type **Description**

--	--

Attachment List

Att Doc Num **Name**

402652272	CEMENT JOB SUMMARY
402652273	OTHER
402652274	OPERATIONS SUMMARY
402652275	WELLBORE DIAGRAM

Total Attach: 4 Files

General Comments

User Group **Comment** **Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)