

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

699502492

FIELD INSPECTION FORM

Loc ID 320225 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccenforcement@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	SI

General Comment:

(This area is currently blank for general comments.)

Location

Lease Road:			
Type	Access		
comment:	road is not maintained very well		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

Good Housekeeping:			
Type	OTHER		
Comment:	No bird protector on separator		
Corrective Action:	Install or repair wildlife protection equipment Comply with rule 324 A.a	Date:	05/20/2019
Type	OTHER		
Comment:	No sign at wellhead		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017
Type	OTHER		
Comment:	Berms need to be repaired around tank		
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.	Date:	10/06/2017
Type	OTHER		
Comment:	No placards on tank/volume/sign		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
	1		STEEL AST		,
Comment:	<input style="width: 100%;" type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 203117 Type: WELL API Number: 001-08525 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: SI
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____
 Comment: no bradenhead test data on COGCC database. Contact COGCC engineering. 04/09/2021
 Corrective Action: Comply with annual bradenhead testing rules. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 3/31/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Linnebur 24-1 Company Name- Fritzler Resources API- 05-001-08525 In Adams County Colorado. While there, I observed SI well. This is a follow up inspection for Document # 685503722 & 88400352 & 685100935 & 685101426 corrective actions from these inspections are delinquent. During this inspection the following possible compliance issues were observed: Berms need to be repaired around tank Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B. 10/6/17 No placards on tank/volume/sign Install sign to comply with Rule 210.d. 10/6/17 No sign at wellhead Install sign to comply with Rule 210.d. 10/6/17 No bird protector on separator Install or repair wildlife protection equipment Comply with rule 324 A.a 5/20/19 no bradenhead test data on COGCC database. Contact COGCC engineering. Comply with annual bradenhead testing rules. 4/9/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	04/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402645821	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391929
699502493	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391925