

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402658006

Date Received:  
04/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
		<u>regulatory@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697502612  
Inspection Date: 02/26/2021 FIR Submit Date: 03/08/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 323461

Location Name: SOONER UNIT-68N58W Number: 28NWNE County: \_\_\_\_\_  
Qtrqr: NWNE Sec: 28 Twp: 8N Range: 58W Meridian: 6  
Latitude: 40.638140 Longitude: -103.865680

FACILITY - API Number: 05-123- -00 Facility ID: 323461

Facility Name: SOONER UNIT-68N58W Number: 28NWNE  
Qtrqr: NWNE Sec: 28 Twp: 8N Range: 58W Meridian: 6  
Latitude: 40.638140 Longitude: -103.865680

CORRECTIVE ACTIONS:

1 CA# 147204

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 04/12/2021

Revegetation activities shall be complete no later than 4/12/20201 or as soon as environmental conditions will permit, as well as fence repairs.

Response: CA COMPLETED Date of Completion: 04/13/2021

Operator Comment: Corrective action is completed, location and access road have been reseeded. See attached photo.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 147205

Corrective Action: Comply with 1002.f; install or repair required BMPs in accordance with good engineering practices.

Date: 04/12/2021

Response: CA COMPLETED

Date of Completion: 04/13/2021

Operator Comment: Corrective action is completed, see attached photo.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton liams

Signed: \_\_\_\_\_

Title: HSE/Regulatory Technician

Date: 4/14/2021 10:47:54 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402658012	Location Photo

Total Attach: 1 Files