

NEW ELK 35-02 API# 05-071-08076 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 15, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103944



PHOTO 1: THE OIL ACCUMULATION ON THE SKID OF THE SCREW COMPRESSOR WAS REMOVED AND THE IMPACTED SOIL ON THE GROUND WAS CLEANED UP.



PHOTO 2:THE IMPACTED SOIL NEXT TO THE SCREW COMPRESSOR WAS REMOVED.