

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2021

Submitted Date:

04/13/2021

Document Number:

693700737

FIELD INSPECTION FORMLoc ID 424744 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Petrie, Erica		erica.petrie@state.co.us	
		dshepard@pedevco.com	
		wboyd@pedevco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463829	SPILL OR RELEASE	AC	04/09/2019		-	Staudinger Heater Treater	EI
479771	SPILL OR RELEASE	AC			-	Staudinger 1-31H	EI

General Comment:

COGCC Environmental Inspection as followup to spill discovered on Inspection 6963031119

Inspected Facilities									
Facility ID:	<u>463829</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>479771</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	Oil impacted material is stockpiled on liner with berm.			
Corrective Action	Provide disposal documentation on Form 19 Supplemental Report when requesting closure			Date: 07/07/2021

Spill/Remediation:

Comment:	Two Spills remain unresolved at this location. 1. Spill ID 479771 discovered on 4/8/2021 by COGCC Inspector. Operator has submitted Form 19-Initial. Form 19 - Supplemental due on 4/18/2021 pursuant to Rule 912.b.(4). Operator has cleaned up standing liquids, stockpiled impacted material and replaced with fresh roadbase. 2. Spill ID 463829 occurred 3/6/2019 at the heater treater and remains unresolved.			
Corrective Action:	1. Operator to obtain confirmation soil samples from material remaining in impacted area and analyze for Table 915-1 constituents as described in Conditions of Approval on Form 19 Doc#402653095. 2. Spill ID 463829 occurred 3/6/2019 at the heater treater and remains unresolved. Operator to submit information required by Conditions of Approval on Form 19-Documents #401985507. Corrective Action Date is to resolve both Spills with information requested on Form 19 Conditions of Approval within 90 days of the more recent Spill. This does not extend the deadline to submit a Form 19 Supplemental Report by April 18, 2019 pursuant to Rule 912.b.(4).			Date: 07/07/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402656426	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401386
693700738	Spill area with fresh road base	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401375
693700739	Well showing release point around rods	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401376
693700740	Impacted material stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401377
693700741	Spill area with fresh road base	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401378