

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2021

Submitted Date:

04/29/2021

Document Number:

689501213**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
,		mknop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478005	SPILL OR RELEASE	CL	12/31/2020		-	H. Huett Consolidation Release	EI

General Comment:

This is a follow-up inspection to Doc # 689501186; environmental inspection of Remediation Project No. 16135/Spill ID 478005(CL). No changes have occurred at the site since the previous inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	No fencing is present around open excavation		
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v.		Date: 04/26/2021

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Excavation was in process at the time of inspection. Excavation has been open since initial inspection conducted 9/16/2020. Form 27 Doc #402653879 (4/9/2021) notes "The excavation as backfilled before samples were taken to confirm clean up at the landowners request to llow cattle in the pasture."

Corrective Action: Per previous CA's Operator shall provide sample location diagram, summary table of analytical results compared to table 915-1 standards, analytical lab reports, any disposal manifests and gate tickets not previously provided, and documentation on the source/location and volume of the clean fill dirt imported on site via Supplemental Form 27 no later than 45 days from the Spill Report Date (10/29/2020). Operator shall submit a Supplemental Form 27 with corrected and accurate narrative regarding its history (4/26/2021).

Date: 10/29/2020

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501214	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5416942