

Well Name: EBC 1, EBC 2, EBC 3, EBC 4, EBC 5, EBC 7 **API #** 05-007-06217
Document Number: 693903090
Inspector: Catherine Roy
Corrective Action: Stormwater BMPs need to be installed to stabilize erosion within the southeastern project area. BMPs need to be installed according to good engineering practices such as those described by CDOT in their erosion control manuals

Correction Action Due: 5/15/2021

Action Completed: 5/5/2021

Action Taken: Placed cobble in area where erosion was occurring. Installed new wattles where existing wattles had been overrun with silt.

