

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2021

Submitted Date:

05/05/2021

Document Number:

689501236

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Brown, Kari 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
,		mknop@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478370	SPILL OR RELEASE	AC			-	Suckla-Brown Unit 17 Header	EI

**General Comment:**

This is a follow-up inspection to Doc #689501188; environmental inspection of Spill ID 478370. No changes have occurred at the site since the previous inspection. Inspection of spill area only; adjacent facilities not inspected. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash/removed flowlines remain on location		
Corrective Action:	Comply with Rule 606		Date: 04/26/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill area has been backfilled. As per email from Operator backfilling occurred 4/18/2021.

Corrective Action: Per COA on Form 19 Document #402517683 submitted on 10/23/2020: Operator will provide documentation justifying closure within 45 days of spill release (11/15/2020). Documentation shall include confirmation soil and groundwater sample analytical data that verifies compliance with Table 915- 1, a sample location diagram, summary table of analytical results compared to table 915-1 standards, analytical lab reports, and disposal manifests. If investigation and remediation require further actions beyond 45 days then submit a Form 27 for approval within 45 days of spill which includes an implementation schedule and remediation workplan for the spill cleanup. Operator is also required to provide an updated root cause of the incident and preventative measures that will be taken to prevent reoccurrence. Please give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal out the extents of the impacts

Date: 11/15/2020

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type \_\_\_\_\_ Management \_\_\_\_\_ Condition \_\_\_\_\_ GPS (Lat) (Long) \_\_\_\_\_

Comment	<u>Oily soils stored on location documented in Inspection #689501175 have been removed.</u>
Corrective Action	<u>Provide disposal manifests and gate tickets for removed soil via Supplemental Form 19</u>
Date:	<u>11/15/2020</u>

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: No BMPs are in place for stormwater management/sediment and erosion control from area disturbed during spill remediation</p> <p>Corrective Action: Install or repair BMPs per Rule 1002.f.(2)C</p> <p>Date: 04/21/2021</p>						
<p><b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402681019	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421731">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421731</a>
689501237	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421708">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421708</a>