

TEP ROCKY MOUNTAIN LLC
GV-67S95W 5NWNW
Location # 334627



TEP ROCKY MOUNTAIN LLC
GV-67S95W 5NWNW
Location # 334627



Culvert between well location and tank battery.

TEP ROCKY MOUNTAIN LLC
GV-67S95W 5NWNW
Location # 334627



Debris and sediment in culvert inlet .



Sediment in culvert outlet.

TEP ROCKY MOUNTAIN LLC
GV-67S95W 5NWNW
Location # 334627



Culvert needs maintained.



Erosion rill running off road.

TEP ROCKY MOUNTAIN LLC
GV-67S95W 5NWNW
Location # 334627



Water/mud hole from storm water collection.

TEP ROCKY MOUNTAIN LLC
GV-67S95W 5NWNW
Location # 334627



Storm flow path.



Sediment over seeded edge of location.