

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/17/2021

Submitted Date:

05/18/2021

Document Number:

693903185

FIELD INSPECTION FORM
 Loc ID 306939 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280417	WELL	PR	04/01/2019	GW	067-09080	WILBOURN FEDERAL 2	RI

General Comment:

On 5/17/2021 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

-Remove and dispose of black netting debris by 6/18/2021.

-Long term stabilization needs to be installed and maintained on upper portions of the well pad cut-slope until stabilized with desirable perennial vegetation. Corrective action date: 6/18/2021.

See below, and attached photos for additional detail.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? **Fail** _____Comment Black plastic netting debris observed across the upper section of the well pad cut-slope.Corrective Action Remove and properly dispose of debris.Date **06/18/2021**Unused or unneeded equipment onsite? **Pass** _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Revegetation is progressing on the well pad fill slopes and lower portion of the cut-slope. However, Desirable vegetation remains sparse and patchy on the upper cut-slope. See corrective action below regarding stabilization and re-seeding on the upper section of the cut-slope. Scattered musk thistles observed, need to be controlled before flowering (by June 1, 2021).

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: 						Date
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:	The upper portions of the well pad cut-slope remain largely bare and exposed with only patchy perennial vegetation.				
Corrective Action:	-Long term stabilization needs to be installed and maintained on upper portions of the well pad cut-slope until stabilized with desirable perennial vegetation. Reseeding should be conducted along with any slope stabilization BMPs. Corrective action date: 6/18/2021.				
Date: 06/18/2021					

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693903186	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432850