

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/13/2021

Document Number:

697601347

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
GINTAUTAS, PETER 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Knop, Max	303-825-4822	MKnop@kpk.com	

**General Comment:**

panel fencing has been used to repair and replace plastic fencing around main spill area  
 Sorbent booms observed in main excavation in effort to minimize transport of crude oil in precipitation event.  
 No barrier to prevent infiltration of crude oil and associated impacts deeper soils and to shallow groundwater at site

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: [panel fencin at site appears to be adequate to limit access by people, wildlife and livestock](#)☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 50

Comment:

PREVIOUS CORRECTIVE ACTIONS REQUIRED THAT FREE HYDROCARBONS  
 BE REMOVED AND THE MIGRATION OF IMPACTS BE LIMITED  
 free hydrocarbons appear  
 to have been removed from visual and olfactory observations

Corrective Action:

Control and contain spills/releases and clean up per Rule 912.a. provide documentation  
 of removal of free product with trucking record and manifest with 10 days (14 May 2021)  
 by FIR corrective action same as in previous inspection

Date: 05/14/2021

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location:

Comment:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402689085	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428736</a>
697601348	metal panel fencing around much of spill area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428716</a>
697601349	green tinted water in wheat field	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428717</a>