

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2021

Submitted Date:

05/14/2021

Document Number:

689501268**FIELD INSPECTION FORM**Loc ID 335610 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
,		mknop@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479618	SPILL OR RELEASE	AC	04/21/2021		-	KIEFER GEORGE W UT B #1A	EI

**General Comment:**

This is a follow-up inspection to Doc #689501238; environmental inspection of Spill ID 479618. Inspection of spill area only; adjacent facilities not inspected. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

[Photos attached to document site conditions.](#)



**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash observed on location (see photo 5).		
Corrective Action:	Comply with Rule 606		Date: 05/20/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Fencing down around open excavation (see photo 1).		
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v.		Date: 05/20/2021

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:







**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill excavation is open (approx. size 25x15x8); no groundwater was observed in the openexcavation. Form 19 (Doc #402625246) lists spill discovery date as 3/9/2021.Corrective Action: As Per Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered, Operator will submit Form 19 Supplemental requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate closure or a Form 27 Workplan with a timeline for investigation and closure of this release. If Remediation will continue under an approved Form 27, also submit a Form 19 Supplemental requesting closure of this spillreferencing the approved Remediation workplan. Operator will provide notice to COGCC EPS Kari Brown (kari.l.brown@state.co.us) at least 48 hours prior to backfill or any sampling events preformed on location. Note that samples collected must be analyzed for Table 915-1 parameters.Date: 06/07/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type \_\_\_\_\_ Management \_\_\_\_\_ Condition \_\_\_\_\_ GPS (Lat) (Long) \_\_\_\_\_

Oily Soil	Pits	Inadequate			
Comment	<u>Approx 30 cu yd of impacted material remain stored on location with inadequate BMPs</u>				
Corrective Action	<u>Manage waste in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.</u>				Date: <u>04/26/2021</u>

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402690231	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429841">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429841</a>
689501274	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429836">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429836</a>