

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/14/2021

Document Number:

697601350**FIELD INSPECTION FORM**Loc ID 467175 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476532	SPILL OR RELEASE	CL	10/27/2020		-	HORST-SCHUTT PW Storage Vessel	CL

**General Comment:**[Environmental inspection of site of spill 476532 with open site investigation and remediation project 14115 at site of spill.](#)[ANY CORRECTIVE ACTION\(S\) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.](#)[waste stockpile volume greatly reduced](#)[Excavation slightly expanded at top edges](#)

Inspected Facilities									
Facility ID:	476532	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	CL

--

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment:	See attached photos The observed storage of waste soils show that the operator has not taken measures to properly store, handle and manage E&P waste to prevent contamination of stormwater, surface water, groundwater and soil as inadequate controls around impacted soils stockpile were observed and soil/groundwater impacts are reported to remain in place and have not been excavated at present.			
Corrective Action:	Comply with rule 913.b(5)B.iv corrective action date remains as in previous inspection 697601264.			Date: 05/20/2021

**Spill/Remediation:**

Comment:	Groundwater is present in the excavation and in contact with impacted soils and free hydrocarbons that were present on groundwater in excavation at previous inspection not visible at this inspection			
Corrective Action:	Document any removal of E&P wastes from site that has occurred since spill was first reported (5/21/2020) by providing haul tickets and manifest for Waste Disposal Per rule 905.b.(3) Provide documentation of transport of exploration and production wastes to offsite facilities to include the following information: A. The date of the transport; B. The identity of the waste generator; C. The identity of the waste transporter; D. The location of the waste pickup site; E. The type and volume of waste; and F. The name and location of the treatment or disposal site. Waste Generator Requirements. Any Operator that generates E&P Waste that is transported off-site will maintain, for not less than 5 years, copies of each invoice, bill, or ticket, and such other records as necessary to document the requirements listed in Rules 905.b.(3).A??F. Such records will be signed by the transporter and provide			Date: 05/20/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402689500	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429233">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429233</a>
697601351	impacted soils stockpile	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429230">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429230</a>
697601352	open excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429231">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429231</a>
697601353	fencing at excavation, impacted soils in background	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429232">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429232</a>