

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402685293

Date Received:
05/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

Jones, Tammy

tajones@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902555

Inspection Date: 11/20/2020

FIR Submit Date: 12/03/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 443138

Location Name: Anderson Number: 2-5H & 3-5H County: LA PLATA

Qtrqtr: SESE Sec: 5 Twp: 32N Range: 6W Meridian: N

Latitude: 37.039400 Longitude: -107.515400

FACILITY - API Number: 05-067- -00 Facility ID: 443139

Facility Name: ANDERSON Number: 3-5H

Qtrqtr: SESE Sec: 5 Twp: 32N Range: 6W Meridian: N

Latitude: 37.039400 Longitude: -107.515400

CORRECTIVE ACTIONS:

1 ☒ CA# 144827

Corrective Action: -Interim reclamation is not conducted. Per 2017 NTO operator's are required to conduct interim reclamation according to rule 1003, or submit a variance for delayed operations and submit bonding in accordance with the NTO. As the well was drilled in 2017, interim reclamation should have been completed no later than spring 2018 (5/15/2018). Corrective action is back dated to document duration of non-complicance.

Date: 05/15/2018

Response: CA COMPLETED

Date of Completion: 05/07/2021

Operator Location and road were cleared of weed debris.
Comment: Location was seeded and straw mulched to establish Interim reclamation growth.
Work was completed on 5-7-21
See attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 144828

Corrective Action: -Weeds are not controlled. Corrective action is back-dated to 5/31/2017 to document original corrective action date for ongoing non-compliance with weeds.

Date: 05/31/2017

Response: CA COMPLETED

Date of Completion: 05/07/2021

Operator Location and road were cleared of weed debris.
Comment: Location was seeded and straw mulched to establish Interim reclamation growth.
Work was completed on 5-7-21
See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 144829

Corrective Action: -Stormwater erosion is not controlled. Corrective action is back-dated to 11/30/2016 to document original corrective action date for ongoing non-compliance with stormwater.

Date: 11/30/2016

Response: CA COMPLETED

Date of Completion: 05/07/2021

Operator Location and road were cleared of weed debris.
Comment: Location was seeded and straw mulched to establish Interim reclamation growth.
Work was completed on 5-7-21
See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 5/11/2021 10:26:49 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402685293	FIR RESOLUTION SUBMITTED
402685300	Resolved Photos

Total Attach: 2 Files